Dane aktualne na dzień: 07-11-2026 02:04

Link do produktu: https://cardsplitter.pl/multimetr-reczny-rebel-rb-830-uniwersalny-dc-ac-750v-p-14402.html



Multimetr ręczny Rebel RB-830 UNIWERSALNY DC AC 750V

Cena	**29,99 zł**
Numer katalogowy	**RB-830**
Kod producenta	**RB-830**
Kod EAN	**5901890058087**
Model	**brak**
Marka	**Rebel**
Kod producenta	**RB-830**
Typ	**ręczny**
Waga produktu z opakowaniem jednostkowym	**0.15**
EAN (GTIN)	**5901890058087**
Informacje o bezpieczeństwie	**CE**
Pomiar	**napięcie przemienne AC**
Maksymalna wyświetlana wartość	**1999**
Rodzaj wyświetlacza	**LCD**

Opis produktu

ZAKRESY POMIAROWE

Napięcie DC: 200 mV, 2000 mV, 20 V, 200 V, 1000 V ±(1%+5)

Napięcie AC: 200 V, 750 V ±(2%+10)

Natężenie prądu DC: 200 µA, 2000 µA, 20 mA, 200 mA, 10 A ±(2%+10)

Rezystancja: 200 Ohm, 2000 Ohm, 20 kOhm, 200 kOhm, 2000 kOhm ±(1%+4)

Test diod

Test tranzystorów hFE

CECHY OGÓLNE

Ręczna zmiana zakresów pomiarowych

Wskaźnik niskiego poziomu baterii

Polaryzacja: automatyczna

Częstotliwość próbkowania: 2 razy na sekundę

Maksymalny odczyt: 1999

Rozmiar wyświetlacza: 45 x 13 mm

Temperatura pracy: 0°C ~ 40° przy wilgotności

Temperatura przechowywania: -10° ~ 50°C przy wilgotności

Zasilanie: bateria 9 V

Wymiary: 122 x 66 x 24 mm

Waga: 107 g

W zestawie: miernik, przewody pomiarowe, instrukcja


Rebel
TOOLS
DIGITAL
MULTIMETER
DC VOLTAGE
AC VOLTAGE
DC CURRENT
RESISTANCE
DIODE
TEST
TRANSISTOR
TEST
model: RB-830
RB-830
DIGITAL
MULTIMETER
COM
TOOLS
model:
RB-830


HV
000
V⎓
1000
200
20
2000m
200m
OFF
750
V~
200
A⎓
2000µ
20m
200
m
10
hFE
2000
k
200k
20k
2000
Ω
200
E
B
C
NPN
PNP
CE
10A⎓MAX
MAX 10SEC
EACH 15MIN
UNFUSED
VΩmA
1000V⎓MAX
750V~MAX
500mA⎓MAX
FUSED
COM
500V≂MAX
Rebel
TOOLS
RB-830BUZ
DIGITAL
MULTIMETER


WARNING
TO AVOID ELECTRICAL SHOCK, REMOVE TEST LEADS BEFORE OPENING CASE.
TO PREVENT FIRE, INSTALL FUSE WITH AMP/VOLT RATINGS SHOWN:
REFER TO MANUAL
POWER SUPPLY: 9V. ONE BATTERY
BATTERY TYPE:NEDA 1604 9V 6F22




Dedra
RB-830BUZ
DIGITAL
MULTIMETER


HV
000
V⎓
1000
200
20
2000m
200m
OFF
V~
750
200
A⎓
2000µ
20m
200m
10
hFE
2000k
200k
20k
2000
Ω
200
NPN
PNP
10A⎓MAX
VΩmA
1000V⎓MAX
750V~MAX
500mA⎓MAX
FUSED
COM
500V⎓MAX
Rebel
RB-830BUZ
DIGITAL
MULTIMETER


WARNING
TO AVOID ELECTRICAL SHOCK,
REMOVE TEST LEADS BEFORE
OPENING CASE.
TO PREVENT FIRE, INSTALL FUSE
WITH AMP/VOLT RATINGS SHOWN.
REFER TO MANUAL
POWER SUPPLY: 9V ONE BATTERY
BATTERY TYPE: NEDA 1604 9V 6F22




HV
000
V⎓
1000
200
20
2000m
200m
OFF
750
V~
200
A⎓
2000µ
20m
200
m
10
hFE
2000
k
200k
20k
2000
Ω
200
E
B
C
NPN
PNP
CE
10A⎓MAX
MAX 10SEC
EACH 15MIN
UNFUSED
VΩmA
1000V⎓MAX
750V~MAX
500mA⎓MAX
FUSED
COM
500V≂MAX
Rebel
TOOLS
RB-830BUZ
DIGITAL
MULTIMETER


WARNING
TO AVOID ELECTRICAL SHOCK, REMOVE TEST LEADS BEFORE OPENING CASE.
TO PREVENT FIRE, INSTALL FUSE WITH AMP/VOLT RATINGS SHOWN:
REFER TO MANUAL
POWER SUPPLY: 9V ONE BATTERY
BATTERY TYPE: NEDA 1604 9V 6F22




HV
000
V⎓
1000
200
20
2000m
200m
OFF
750
V~
200
A⎓
200µ
2000µ
20m
200m
10
2000
k
200k
20k
2000
Ω
200
hFE
E
B
C
NPN
PNP
10A⎓MAX
MAX 10SEC
EACH 15MIN
UNFUSED
VΩmA
1000V⎓MAX
750V~MAX
500mA⎓MAX
FUSED
COM
500V⎓MAX
Rebel
TOOLS
RB-830
DIGITAL
MULTIMETER


HV
000
V⎓
1000
200
20
2000m
200m
OFF
750
V~
200
A⎓
200µ
2000µ
20m
200m
10
2000
k
200k
20k
2000
Ω
200
hFE
E
B
C
E
C
E
NPN
PNP
CE
10A⎓MAX
MAX 10SEC
EACH 15MIN
UNFUSED
VΩmA
1000V⎓MAX
750V~MAX
596mA⎓MAX
FUSED
COM
500V⎓MAX
Rebel
TOOLS
RB-830
DIGITAL
MULTIMETER

